

Assembly

STEP 2

Remove the zip tie and protective material as shown in the picture and then plug in the power, after 2 minutes, press "+" button twice to add air into the piston, let the cable slowly go back in the main frame, after the cable go back completely, please unplug the power.

